

STORMWATER FUEL CLEAN-UP GUIDELINE FOR PROJECTS COVERED UNDER THE CGP

NOT TO SCALE

MINIMUM REQUIREMENTS

ALL FUEL SPILLS GREATER THAN 25 GALLONS MUST BE REPORTED TO THE TCEQ (432-570-1359)

AND TO THE CITY OF ODESSA (432-335-3290) IMMEDIATELY UPON DISCOVERY.

AT NO POINT DURING THE CLEAN-UP CAN ANY OF THE CONTAMINATED SOILS BE PLACED INTO ANY CITY OF ODESSA WASTE CONTAINERS, ALL QUALIFYING AMOUNTS OF CONTAMINATED SOILS MUST BE TAKEN TO PROPER DISPOSAL FACILITIES.

FUEL SPILLS



a) SPILLS LESS THAN 1 SQ. FT. (SURFACE AREA)



- i) REMOVE ALL SIGNS OF VISIBLE STAINING
- ii) TAKE FUEL LADEN MATERIAL TO LOCAL DISPOSAL FACILITY
- iii) DOCUMENT SPILL CAUSE AND CORRECTIVE ACTION IN SWPPP
 - 1) CAUSE (WHY IT HAPPENED)
 - 2) CORRECTIVE ACTION IN SWPPP (HOW DID YOU FIX IT)
 - 3) INCLUDE DISPOSAL RECEIPTS

b) SPILLS GREATER THAN 1 SQ. FT. BUT LESS THAN 8 SQ. FT. (SURFACE AREA)

- i) REMOVE ALL SIGNS OF VISIBLE STAINING
- ii) TAKE FUEL LADEN MATERIAL TO LOCAL DISPOSAL FACILITY
- iii) TEST BOTTOM OF PIT FOR BTEX FLAG LOCATION WAS TAKEN FROM
- iv) CALL FOR AN INSPECTION FROM THE STORMWATER DEPARTMENT TO VERIFY REMOVAL AND CLEAN TEST RESULTS
- v) DOCUMENT SPILL CAUSE AND CORRECTIVE ACTION IN SWPPP
 - 1) CAUSE (WHY IT HAPPENED)
 - 2) CORRECTIVE ACTION IN SWPPP (HOW DID YOU FIX IT)
 - 3) INCLUDE DISPOSAL RECEIPTS



c) SPILLS GREATER THAN 8 SQ. FT. (SURFACE AREA)

- i) REMOVE ALL SIGNS OF VISIBLE STAINING
- ii) TAKE FUEL LADEN MATERIAL TO LOCAL DISPOSAL FACILITY
- iii) TEST BOTTOM OF PIT AND SIDES FOR BTEX FLAG LOCATION TEST WAS TAKEN FROM
- iv) CALL FOR AN INSPECTION FROM STORMWATER DEPARTMENT TO VERIFY REMOVAL AND CLEAN TEST RESULTS
- v) DOCUMENT SPILL CAUSE AND CORRECTIVE ACTION IN SWPPP
 - 1) CAUSE (WHY IT HAPPENED)
 - 2) CORRECTIVE ACTION IN SWPPP (HOW DID YOU FIX IT)
 - 3) INCLUDE DISPOSAL RECEIPTS

DRAWN BY: JStewart/La
 DATE: April 23, 2015
 SCALE: N.T.S.